Portek LTD
www.portek.co.uk

SPRAY MAXX

WARNINGS:
AFTER USE, RELEASE ANY REMAINING PRESSURE BY LIFTING THE QUICK RELEASE PRESSURE RELIEF VALVE (7) UPWARD. **DO NOT** STORE SPRAYER PRESSURISED, ENSURE TRIGGER LOCK IS RELEASED.

3 PUMP HANDLE (3) UNTIL RESISTANCE IS FELT (APPROXIMATELY 30 STROKES).

7

4 SPRAY BY PRESSING DOWN BUTTON (4)

5 FOR CONTINUOUS SPRAYING PRESS BUTTON (4) DOWN AND SLIDE THE TRIGGER LOCK (5) FORWARD

6 ADJUST SPRAY PATTERN BY ROTATING NOZZLE (6)

2 FIRMLY CLOSE THE SCREW CAP (2)

2.0L
1.5L
1.0L
0.5L

1 FILL THE SPRAYER AS FAR AS THE 2.0 LITRE FILL LINE (1). **DO NOT** OVERFILL OTHERWISE THE SPRAYER MAY NOT PROVIDE FULL PRESSURE.



2.0